

Precision Tension and Compression Load Cell

MODEL 8524



Large measuring ranges



Medium measuring ranges (with accessories)



Small measuring ranges

Highlights

- Measuring ranges from 0 ... 500 N up to 0 ... 200 kN
- Non-linearity 0.25 % F.S.
- Particularly versatile
- Cable suitable for drag chains and highly flexible

Options

- Non-linearity 0.1 % F.S.
- Extended temperature range of -30 ... +120 °C
- Standardized nominal sensitivity 1.5 mV/V
- burster TFDS
- Overload protection up to 5 times the nominal force
- Pull plate and rod end bearings

Applications

- All areas of mechanical engineering
- Assembly and joining equipment
- Hydraulic presses
- Measurement of cable strengths

Product description

The 8524 precision tension & compression load cell is a versatile sensor for highly accurate load measurements in diverse applications. Optimum measurement quality is achieved with the load cell mounted on a flat, hard and polished contact surface. This requirement does not apply to small measurement ranges of up to 0 ... 2 kN because three knife-edge bearings ensure that the sensor is seated securely. Off-center forces, bending moments and torques of less than 5% of the rated load will not impair the sensor's measurement quality. Our brochure "Load Cells" explains how you can design parasitic loads out of your mechanical system.


Through-holes in the outer flange are used for fastening the 8524 sensor to the system structure. The load is applied via the central blind threaded hole or optionally via a load button. Alternatively, a pull plate and even rod end bearings, if desired, can be attached to the sensor for equally easy measurement of purely tensile loads, for instance in Bowden cables or chains. The 8524 sensor is designed to measure static, quasi-static and dynamic compressive and/or tensile loads.


Inside the sensor is an elastic membrane, on which are applied strain gages connected in a full Wheatstone bridge. If a tensile or compressive load is applied to the sensor, the ohmic resistance of the measuring bridge changes and detunes the output signal in proportion to the measured load in mV/V.


8524	-	5500	6001	6002	6005	6010	6020	6050	6100	6200
Measuring range		±0,5 kN	±1 kN	±2 kN	±5 kN	±10 kN	±20 kN	±50 kN	±100 kN	±200 kN
calibrated in N and kN from 0		±112.4 lbs	±224.8 lbs	±449.6 lbs	±1.1 klbs	±2.2 klbs	±4.5 klbs	±11.2 klbs	±22.5 klbs	±45.0 klb
Accuracy										
Relative non-linearity*					0.25 % F	S. (option: 0).1 % F.S.)			
Characteristic curve deviation*						0.25 % F.S.				
Relative hysteresis		0.2 %	% F.S.				0.25 % F.S.			
Temperature effect on zero output					≤	0.02 % F.S.,	/K			
Temperature effect on nominal sensitivity					≤	0.02 % F.S.,	/K			
Electrical values					\/ \/ \/				ı	
Sensitivity nominal						ession direct	•			
Measurement direction					is likely to b	on. Load cali e different wl	hen used in			
Standardization		realized or	n an circuit b		mm (L x W)		after 1.7 m		or 0.3 m from	cable end
Bridge resistance						al (deviation:		•		
Excitation				recomm		C or AC / n		C or AC		
Insulation resistance					> 3	$30~{ m M}\Omega$ at 45	5 V			
Environmental condi	tions									
Nominal temperature range					+1	5 °C +70	°C			
Operating temperature range					-30) °C +80	°C			
Mechanical values										
Deflection full scale		< 80 µm								
Maximum operating force		150 % of capacity								
Overload burst		> 250 % of capacity								
Dynamic performance		recommended: 70 %: maximum: 100 % (of capacity)								
Material			stainless steel 1.4542							
Protection class (EN 60529)				IP65				IP	67	
Geometry		5500	6001	6002	6005	6010	6020	6050	6100	6200
Ø D1	[mm]			54.5			79.0	119.0	15	5.0
Ø D2	[mm]		15.0		15	5.0	22.0	44.0	60	0.0
Ø D3	[mm]			35.5			59.0	94.0	10	9.0
Ø D4	[mm]		33.5		34	1.5	58.6	92.6	10	7.0
Н	[mm]		16.0 + 1.0		10	5.0	25.0	35.0	50	0.0
G	[mm]			45.0			68.0	105.0	12	9.0
ØX	[mm]			4	.5			6.6	13	1.5
ØY	[mm]			8	.0			11.0	20	0.0
Central blind threaded hole T				M8 x 1.25	i		M12 x 1.5	M24 x 1.5	M36	x 3
Number of clearing holes in Ø		3 (with edges, H + 1 mm) 6 8					8			
Dimensional drawings		dimer	nsional draw	ving 1	dimensiona	l drawing 2	С	limensional d	drawing 3 &	4
Installation										
Intended mounting screws				٨	۱4			M6	М	12
Tightening torque mounting screws	[N*m]							00		
Mounting screws					resista	nce 12.9 or	higher			
Installation instructions		The entire bearing area of the sensor must be mounted on a base which is hardened (60 HRC), flat, polished or better lapped. Counter bores in compliance with DIN 74-km, in compliance with DIN 912 head cap screws								
Other					110	Jup Jule				
Natural frequency	[kHz]	> 2	> 3	> 5	> 8	> 12	> 4		3	> 5
• •		- / 4	_ / J	0.25		<i>-</i> 12	0.65		5	
Mass	[kg]			0.25			0.65	2.0	3	.0















^{**} at standardization or cable extension



Electrical termination

Output signal

burster load cells are based on a strain-gage Wheatstone bridge. This measurement principle means that the output voltage mV/V is highly dependent on the sensor supply voltage. Our website contains details of suitable instrumentation amplifiers, indicator and display devices and process instruments.




8524	-	5500	6001	6002	6005	6010	6020	6050	6100	6200
Measuring range from 0		±0.5 kN	±1 kN	±2 kN	±5 kN	±10 kN	±20 kN	±50 kN	±100 kN	±200 kN
Electrical termination										
Cable specifications		Highly fle	Highly flexible, oil resistant, drag chains suitable. Bending radius three times the diameter for fixed cable, ten times the diameter for cable permanently moving.							
Cable model		PUR, Ø = 4.2 mm								

Options

Overload protection in compression direction

The optional overload protection guards a load cell against damage under a static load that exceeds the safe load (150% of the rated load). The overload protection is available up to the measurement range of ≤ 20 kN. Protection is achieved via a mechanical stop, which limits the measurement displacement of the sensor (to about 80 μm). The overload protection contains additional holes for mounting on a fixed system structure, which then allows the transmission and measurement of tensile loads as well.


- Overload protection for compression only
- Measuring tension and compression load
- Overload protection mounting by factory only
- Tolerance of standardized output with overload protection at 0.5 % F.S.
- Do not use the overload protection often
- Overload protection does not have any centric threaded holes



Order number	see order code									
Compatible for measuring range from 0		±0.5 kN	±1 kN	±2 kN	±5 kN	±10 kN	±20 kN	-	-	-
Geometry										
Ø D1		54.5					79	-	-	-
H1		19					25	-	-	-
Н		16					25	-	-	-
Other										
Mass	[kg]		0.3		0.	.7	0.8	-	-	-

Pull plates

A pull plate extends the range of potential uses of tension & compression load cells to measuring tensile loads in moving assemblies (cable tension or forces in joints). The pull plate is fastened by its outer flange to the sensor's flange. Customized threaded parts or even rod end bearings can be fitted in the central threaded hole. Once fitted, the pull plates form part of the sensor. Sensor and plate are calibrated as a unit and are supplied only as a pre-assembled combination. Bolts of strength 12.9 are required for fitting the pull plates.




Order number		see order code								
Compatible for measuring range from 0		±0.5 kN	±1 kN	±2 kN	±5 kN	±10 kN	±20 kN	±50 kN	±100 kN	±200 kN
Geometry										
Central blind threaded hole T		M8 x 1.25					M12 x 1.5	M24 x 1.5	M36 x 3	
Installation										
Tightening torque mounting screws	[N*m]	3					10			
Other										
Mass	[kg]	0.28				0.7	2.2	5	.5	

Accessories

Rod end bearings

The 8524 load cell can be optionally supplied with a rod end bearing. In combination with a pull plate (see option), up to two rod end bearings can be used. Rod end bearings ensure optimum load application when the sensor is used in the tension direction. In addition, they can compensate for slight misalignment in the compression direction.

- Optimal force introduction
- Compensation of misalignments
- Very high dynamic und static load capacity
- Material: stainless steel
- Temperature range: 45 °C to + 120 °C
- PTFE insert, maintenance-free
- DIN 648 series K
- Bore holes H7, recommended connection pin: g6
- Inner ring not suitable for permanent rotary operation




Order Code

8591	-	Z08M	Z12M	Z36M
В	[mm]	12	16	43
М	[mm]	9.00	12.00	28
Α	[mm]	24	32	80
F	[mm]	42	54	125
L	[mm]	54	70	165
0	[mm]	10.4	15.4	37.7
D	[mm]	8	12	35
G		M8 x 1.25	M12 x 1.5	M36 x 3.0
GL	[mm]	25	33	73
α	[°]	14	13	19
Other				
Stat. load factor	[kN]	19.5	42.0	230.0
Dyn. load factor	[kN]	16.7	32.0	205.0
Weight	[g]	33	87	1600

Load buttons

Load buttons are used when purely compressive forces are meant to be applied to the load cell and when direct coupling to the surrounding mechanical structure via the central threaded hole in the sensor is not required/possible. The domed surface of the load button minimizes angle errors for loads applied at an angle of up to 3° . The compressive force must be applied to the button via a flat and hardened contact surface. The optimum hardness is 60 HRC or more.



Order Code

8580	-	V008					V012	V024	V0	36
Compatible for measuring range from 0		±0.5 kN	±1 kN	±2 kN	±5 kN	±10 kN	±20 kN	±50 kN	±100 kN	±200 kN
Geometry										
ØD	[mm]			14.0			20.0	40.0	57.0	
Н	[mm]	7.3						20.0	30.0	
L	[mm]	7.0					12.0	1 <i>7</i> ,0	40.0	
Т		M8 x 1.25					M12 x 1.5	M24 x 1.5	M: x	
SW	[mm]		-			16	32	46	0.0	
R		20					25	100	20	0.0
Installation										
Tightening torques	[N*m]	max. 5			ma	x. 8	max. 10	max. 20	max	. 50
Other										
Mass	[kg]	0.01					0.05	0.25	•	

Connectors and units

Order Code

Connectors					
9941	Connectors 12 pin, suitable to all burster desktop units				
9900-V209	Connectors 9 pin, suitable to SENSORMASTER, DIGIFORCE® and TRANS CAL				
9900-V229	Connectors 9 pin with TEDS				
9900-V245	Connectors 8 pin, suitable to ForceMaster				
Units					
7281-V0001	Mobile measuring device with strain gage simulator and sensor test (R _i , R _a , Shunt, R _{ISO})				
refer to section 9	Sensor electronics, amplifier and process control units like digital indicator model 9180, model 9163, modular amplifier model 9250 or DIGIFORCE® model 9307				

Calibration

Test and calibration certificate							
Included in scope of delivery of sensor	Amongst other data, includes figures for zero point, full-scale output and calibration offset						
Standard factory calibration	Standard factory calibration certificate for load cells or measurement chains (WKS)						
Optionally available	Our standard factory calibration certificate includes 11 measurement points, starting at zero, spread evenly in 20% steps over the full measuring range, for increasing and decreasing load under the same installation conditions. Factory calibrations can be performed in the compression and/or tension direction depending on the sensor type.						
Special factory calibration	certificate for load cells or measurement chains (WKS)						
On request	We are happy to calibrate sensors and measurement chains to the customer's specification.						
German-accredited DAkkS calibration certificate for sensors and measurement chains (DKD)							
Optionally available	Our DAkkS-certified calibration laboratory provides calibration certificates to DIN EN ISO 376. The calibration certificate includes 21 measurement points, starting at zero, spread evenly in 10% steps over the measuring range, for increasing and decreasing load under various installation conditions. DAkkS calibrations can be performed in the compression and/or tension direction depending on the sensor type.						



Measuring range

±0.5 kN

Measuring range
0 ... ±112.4 lbs

Code

0

5

Note

■ Brochure

Pull plate

Our brochure **"Load cells for production, automation, R&D and quality assurance"** is available for download on our website. It conatains numerous applications, detailed product specifications and overviews.

Product videos

Watch our How-to-do video at: www.youtube.com/bursterVideo

Overload protection in compression direction (only for ranges up to 0 ... 20 kN)

■ Nominal temperature range +15 °C ... +70 °C





Download via www.burster.com or directly at www.traceparts.com

