

Ultra-Miniature Load Cell

MODEL 8416





Option Non-linearity ≤ ±0.15 % F.S.



Model 8416 original size

Highlights

- Measuring ranges from 0 ... 20 N up to 0 ... 5 kN
 0 ... 4.5 lbs up to 0 ... 1124.0 lbs
- Dragchain cable
- Inexpensive
- Minimum diameter

Options

- burster TEDS
- Temperature compensated range -40 °C ... +90 °C
- Standardization of the nominal sensitivity
- Connection cable from single strand

Applications

- Equipment construction
- Production lines
- Measuring and control equipment
- Testing systems
- Handling gear

Product description

Due to their extremely compact design, these load cells can be used wherever static or dynamic load forces have to be measured in very tight spaces.

Model 8416 is perfect for use in micro-technology and just as suitable for measuring tasks in the research and development sector.


The ultra-miniature compression load cell model 8416 is a flat, circular disc, the bottom of which is sealed with a cover. The load application button for receiving the compression forces is an integrated part of the sensor.

The sensor element inside the body carries a strain gage full bridge which outputs voltage directly proportional to the measurement variable upon application of force.

The short nominal measurement distance of the ultra-miniature compression load cells due to their design provides a high degree of rigidity. If needed, the nominal characteristic value can be standardized in the sensor connection cable. This allows for quick and easy interchange or simultaneous connection of several sensors to a single evaluation unit.

8416	-	5020	5050	5100	5200	5500	6001	6002	6005		
Measuring range		20 N	50 N	100 N	200 N	500 N	1 kN	2 kN	5 kN		
calibrated in N and kN from 0		4.5 lbs	11.2 lbs	22.5 lbs	45.0 lbs	112.4 lbs	225.0 lbs	450.0 lbs	1124.0 lbs		
Accuracy											
Relative non-linearity*			$\leq \pm 0.25$ % F.S. (option $\leq \pm 0.15$ % F.S.)								
Characteristic curve deviation*				≤ ±0.5 % F.S.	≤ ±1.0 % F.S.						
Relative hysteresis				≤ ±0.2	5 % F.S.			≤ ±0.3 % F.S.	≤ ±0.5 % F.S.		
Temperature effect on zero output			≤ ±0.3 % F.S./10 K								
Temperature effect on nominal sensitivity			≤ ±0.3 % F.S./10 K								
Electrical value											
Sensitivity nominal		1 mV/V									
Measurement direction			compression direction								
Standardization		option 0.8 mV/V (±0.5 %) realized on board in connection cable, 1.7 m from sensor housing or 0.3 m from cable end									
Bridge resistance			350 Ω nominal (deviations are possible)								
Excitation					max. 5 V	DC or AC					
Insulation resistance					> 30 Mg	2 at 45 V					
Environmental condi	tions										
Nominal temperature range					+15 °C .	+70 °C					
Operating temperature range			0 °C +80 °C								
Mechanical values											
Deflection full scale					20	μm					
Maximum operating force					150 % o	f capacity					
Overload burst					> 250 % (of capacity					
Dynamic performance			recommended: 70 % of capacity maximum: 100 % of capacity								
Protection class (EN 60529)		IP54									
Other		5020	5050	5100	5200	5500	6001	6002	6005		
Material					stainless st	eel 1.4542					
Natural frequency	[kHz]	6	6	6	20	18	30	45	80		
Mass without cable	[g]				1	0					

^{*} The data in the area 20 % - 100 % of rated load F




8416	-	5020	5050	5100	5200	5500	6001	6002	6005		
Measuring range from 0		20 N	50 N	100 N	200 N	500 N	1 kN	2 kN	5 kN		
Geometry											
Ø D1	[mm]		10.6								
Ø D2	[mm]		3								
Ø D3	[mm]	8.	8.3 7.65								
H 1	[mm]		4.5			5.5	6.5		6.9		
H 2	[mm]	5			6	7	7	7.5			
General tolerance of dimension		ISO 2768f									

Mounting	
Mounting instructions	The measurement force must be introduced centrically and without any lateral forces. To prevent contact at just a few points, ensure that the sensor is installed on a flat surface.
	The sensor can be secured, for example, with silicon, wax or adhesive cement. Do not subject the sensor to lateral clamping forces as these would lead to measurement errors.
	When handling and installing the sensor, ensure that the cable outlet and sensor cable are not subject to excessively high tensile or lateral forces. Strain relief may be necessary.

Electrical termination

Output signal

burster load cells are based on a strain-gage Wheatstone bridge. This measurement principle means that the output voltage mV/V is highly dependent on the sensor supply voltage. Our website contains details of suitable instrumentation amplifiers, indicator and display devices and process instruments.



8416	-	5020	5050	5100	5200	5500	6001	6002	6005		
Measuring range from 0		20 N	50 N	100 N	200 N	500 N	1 kN	2 kN	5 kN		
Electrical termination											
Specifications		shielded, PTFE coated, 4 wire cable with bare ends for soldering, cable length 1.7 m, drag chain									
Cable fastening		cable cover									
Bending protection		without									
Bending radius			≥ 6 mm rigidly laid; ≥ 20 mm moving at temperatures > -20 °C moving connection cable not approved								

Accessories

Connectors and units

Order code

Connectors							
9941	Connectors 12 pin, suitable to all burster desktop units						
9900-V209	Connectors 9 pin, suitable to SENSORMASTER, DIGIFORCE® and TRANS CAL						
9900-V229	Connectors 9 pin with TEDS						
9900-V245	Connectors 8 pin, suitable to ForceMaster						
Units							
7281-V0001	Mobile measuring device with strain gage simulator and sensor test (R _i , R _a , Shunt, R _{ISO})						
refer to section 9	Sensor electronics, amplifier and process control units like digital indicator model 9180, model 9163, modular amplifier model 9250 or DIGIFORCE® model 9307						

Calibration

Test and calibration certificate								
Included in scope of delivery of sensor	Amongst other data, includes figures for zero point, full-scale output and calibration offset							
Standard factory calibration certificate for load cells or measurement chains (WKS)								
Optionally available	Our standard factory calibration certificate includes 11 measurement points, starting at zero, spread evenly in 20% steps over the full measuring range, for increasing and decreasing load under the same installation conditions.							
Special factory calib	ration certificate for load cells or measurement chains (WKS)							
On request	We are happy to calibrate sensors and measurement chains to the customer's specification.							
German-accredited [German-accredited DAkkS calibration certificate for sensors and measurement chains (DKD)							
Optionally available	Our DAkkS-certified calibration laboratory provides calibration certificates to DIN EN ISO 376. The calibration certificate includes 21 measurement points, starting at zero, spread evenly in 10% steps over the measuring range, for increasing and decreasing load under various installation conditions. DAkkS calibrations can be performed in the compression and/or tension direction depending on the sensor type.							



Order Code

Measuring range Code Measuring range								
0 20 N 5 0 2 0 0 4.5 lbs								
0 50 N 5 0 5 11.2 lbs								
0 100 N 5 1 0 0 0 22.5 lbs								
0 200 N 5 2 0 0 0 45.0 lbs								
0 500 N 5 5 0 0 0 112.4 lbs								
0 1 kN 6 0 0 1 0 225.0 lbs								
0 2 kN 6 0 0 2 0 450.0 lbs								
0 5 kN 6 0 0 5 0 1124.0 lbs								
Delivery ex stock at short	t notice							
N 0 0 S	0	0	0					
8 4 1 6 0	0	0						
■ Nominal sensitivity/not standardized								
■ Standardization at 0.8 mV/V								
■ Connection cable 1.7 m (with standardization in the cable 2 m)								
■ Connection cable 3 m								
■ Connection cable 5 m								
■ Connection cable 3 m, extended by a circuit board at 1,7 m *								
■ Connection cable 5 m extended *								
* shortened delivery time compared with cable length 3 m and 5 m in one piece								
■ Open cable ends + 6 cm single strands								
9 pins Sub-D connector model 9900-V209								
9 pins Sub-D connector model 9900-V209 for 9163-V3xxxx								
■ 12 pins round connector model 9941 for burster desktop devices F								
■ 9 pins Sub-D connector with burster TEDS model 9900-V229 T								
Near line with a recording to the secretic setting *								
Non-linearity according to specification *								
■ Relative non-linearity ≤ ±0.15 % F.S. * * The data in the area 20 % · 100 % of rated load F								
THE data in the died 20 % - 100 % of Idled load I								
■ Temperature compensated range +15 °C +70 °C			0					
■ Temperature compensated range +15 °C +70 °C ■ Temperature compensated range -40 °C +90 °C								

Note

Brochure

Our brochure **"Load cells for production, automation, R&D and quality assurance"** is available for download on our website. It conatains numerous applications, detailed product specifications and overviews.

Product videos

Watch our How-to-do video at: www.youtube.com/bursterVideo





Download via www.burster.com or directly at www.traceparts.com

